



If H or W is 4 or less then connector slots along that dimension will be reduced to 1 centered slot.  
 If H or W is 12 or more then wireway will receive an additional connector slot centered along that dimension.