



If  $W$  is 4 or less then Mounting holes along that dimension will be reduced to 1 centered Mounting hole.  
 If  $W$  is 12 or more then wireway will receive an additional Mounting hole centered along that dimension.