



If  $H$  or  $W$  is 4 or less then connector slots along that dimension will be reduced to 1 centered slot.

If  $H$  or  $W$  is 12 or more then wireway will receive an additional connector slot centered along that dimension.